

TROUBLESHOOTING: LOW AUDIO OUTPUT

On some amplified Honda applications, the factory amplifier may receive an audio signal that is not at the expected input level when using an aftermarket radio. This can result in very low audio volume, even when the aftermarket radio's volume is turned up.

To correct this condition, a High-to-Low Level Converter (LOC) must be used as shown below. The LOC converts the aftermarket radio's speaker-level (high-level) output to the appropriate low-level signal for the factory amplified audio system.

If you experience low audio output after installation, follow the High-to-Low Adapter connection instructions below.

