



Video In Motion Activation for Audi and Volkswagen Vehicles with MIB1 & MIB2 Systems

Vehicle Applications

2013 – Up	Α3
2016 – Up	A4
2015 – Up	Α6
2016 – Up	Α7
2016 – Up	Α8
2016 – Up	Q7

VOLKSWAGEN (6.5" & 7" Screen)

2015 – Up	Golf 7
2016 – Up	Passat
2016 – Up	Tiguan



2015 Audi A3



2015 VW Golf



2016 Audi A4



2016 VW Tiguan



2015 Audi A6




2016 Passat



- No need to remove the radio just plug into the OBD II port.
- Retains functionality of Factory-installed Navigation System for passenger access at anytime.

L/2 Rev.112116





tel. #: (818) 609-9299 fax #: (818) 996-8188





Video In Motion Activation for Audi and Volkswagen Vehicles with MIB1 & MIB2 Systems



- Compatible with: VW MIB Composition Media (6.5"/7") and AUDI MIB MMI Navigation (7") systems.
- Not compatible with Touch Screen systems.

Parts Included





OBD II PLUG

Installation Instructions

- 1. Locate OBD-port and remove cover.
- 2. Turn on ignition.
- 3. Wait until the head-unit has completely booted.
- 4. Plug the VIMAD-840 into OBD-port which is usually located under the steering column.
- 5. Leave coder for about 30 seconds in OBD-port until the Green LED has a steady light.
- 6. Remove coder from the OBD-port.

To reverse the coding repeat steps 1-6.

After the first use on a vehicle, the VIMAD-84O is personalized to this vehicle and can be used unlimited times to code or reverse coding on this vehicle only.

LED Information:

LED	Status	Description
Cross Solid Coding procedure successfully completed		Coding procedure successfully completed
Green Flashing	Flashing	Coding process in progress
Solid		Remove coding procedure successfully completed
Red Flashing	Flashing	Coding process failed / license violation
Green + Red	Solid	CAN Communication Error! - Abort coding session

7.2 3.5 30.2