



Radio Replacement Interface for GM Class II Vehicles with Factory Amplified (Bose/Monsoon) and Non-Amplifed Audio Systems

PRODUCT FEATURES:

- Retains factory features in select GM Class II Data Bus vehicles while functioning with an aftermarket radio.
- Supports Bose, Monsoon, Y-91 audio* and non-amplified audio systems.
- Retains chime functions.
- Built-in chime volume adjustment.
- EIA color coded wiring for easy installation.

*Does not retain Y-91 Premium Bose amplifier on 2002-2004 trucks and SUVs; use part# SWRGM-48 instead.

PARTS INCLUDED:








SOCGM-17C Harness

INSTALLATION DIAGRAM:





rev.09282021





Radio Replacement Interface for GM Class II Vehicles with Factory Amplified (Bose/Monsoon) and Non-Amplified Audio Systems

SELECTING THE AUDIO SYSTEM:


If the vehicle is equipped with an amplified audio system, the SOCGM-17C has a built-in audio level adaptor that outputs the proper audio level from the aftermarket radio to the factory amplifier. To use this feature, plug in the male 8-pin connector on the SOCGM-17C harness to the GRAY female 8-pin connector on the SOCGM-17C module. The module is also labeled "Bose" and "Non Bose" to avoid confusion. (see picture below)

If the vehicle is NOT equipped with a factory amplified system, plug in the male 8-pin connector to the BLACK female 8-pin on the SOCGM-17C module.



CHIME VOLUME ADJUSTMENT:

The SOCGM-17C has a potentiometer to adjust the chime volume. It is set at half way by default. To adjust the volume, simply use a suitable screw driver and turn the potentiometer clockwise to increase the volume and counter-clockwise to decrease the volume.







Radio Replacement Interface for GM Class II Vehicles with Factory Amplified (Bose/Monsoon) and Non-Amplified Audio Systems

VEHICLE APPLICATIONS:

Buick		GMC	
2004-2005	Century	20042011	Canyon
2005-2007	LaCrosse	2002-2009	Envoy
2004-2007	Rainier	2003-2007	Savana
2003-2005	Rendezvous	2003-2006	Sierra
2005-2007	Terraza	2007	Sierra Classic
		2003-2006	Yukon
Cadillac			
2004-2006	Escalade	Hummer	
		2003-2007	H2
Chevrolet		2005-2009	H3
2003-2006	Avalanche		
2000-2005	Cavalier	Isuzu	
2004-2013	Colorado	2003-2008	Ascender
2006-2013	Corvette		
2004-2007	Express	Oldsmobile	
2000-2005	Impala	2001-2004	Alero
2000-2005	Monte Carlo	2002-2004	Bravada
2003-2004	S-10	2000-2004	Silhouette
2003-2006	Silverado		
2007	Silverado Classic	Pontiac	
2003-2006	SSR	2001-2005	Aztek
2003-2006	Suburban	2001-2005	Grand Am
2003-2006	Tahoe	2004-2008	Grand Prix
2002-2009	Trailblazer	2000-2006	Montana
2005-2008	Uplander	2000-2005	Sunfire
2003-2005	Venture		
		Saab	
		2005-2008	9-7X
		Saturn	
		2005-2007	Relay

NOTE:

There are instances on the Corvette when the chime will sound when either the "Traction Control" or the "DIC" (Driver Information Center) buttons are pressed.



Traction Control Button



Driver Information Center Buttons



rev.09282021